

REPORT of SURVEY for REPAIRS &c.

No. 1132

No. in
Reg. Book.

Survey held at

Dublin

Date, first Survey

13 Oct 1880

Last Survey

18

404 on the

Iron Ship Scottish Chieftan

Master

J Hamilton

TONNAGE under Tonnage Deck

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St'mer, cut on Bm.

Built at

Stockton

When built

1876

YEAR.

MONTH.

Owners

W. H. Ross & Co

Port belonging to

Liverpool

Residence

Liverpool

By whom built

Richardson

Destined Voyage

If Surveyed Afloat or in Dry Dock

In dry Dock

Length of Poop

ft.

Ditto, Forecastle

ft.

Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Last Survey, No.

23581

Port

Iron

Classed

100 A 1

REPAIRS, OR EXAMINATION AS PER RULE

SS N° 1

Being now due on this Ship

The Owners are desirous to have her only Partly surveyed in Dublin and completed after arrival at Cardiff, when the Ballast amidships will be removed

Now done at Dublin in accordance with Rule
Placed on Blocks in Dry dock - Bottom & Keel scraped clean - found in good order - Two coats of Composition has now been put on -

Aft - The timber boards & ceiling lifted from the water tank about the Mainmast to right close aft
Forward - From about 10 feet 7 part of Main Hatch forward The Cementing in those parts has been examined and proved in good condition and adhering satisfactory to the Iron, excepting in one small patch (forward) which has now been renewed

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigginy

The Amount of Entry Fee

received by me,

Special

2 : 2 : 0

187

Certificate (if required)

(Travelling Expenses, if any, £)

Committee's Minute

Tuesday, November, 16th 1880.

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.



Lloyd's Register
Foundation

IRON 496-0325