

REPORT of SURVEY for REPAIRS, &c.

28419

(Received at London Office, 17/11/80)

Re 9813
 Survey held at London Date, first Survey 6th Nov Last Survey 15th Nov 1880
 on the Iron B^{ke} "Verulam" Master Lloyd J. G. Elliott
 L GE under Tonnage Deck 303 Built at Greensck When built 1876
 D Spar Deck, or Awning Deck Owners Bullard & King Port belonging to London
 Ditto of Poop Residence
 Ditto of Raised Qr. Dk. By whom built J. E. Scott Destined Voyage Katal
 Ditto of Houses on Deck If Surveyed Afloat or in Dry Dock Horseferry dry Dock Afloat
 Ditto of Forecastle Gross Tonnage 347
 Net Space, as per Rule Register Tonnage, cut on Beam 334
 Engine Room
 Tons as St mer, cut on Bm.

L of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned. Character in Register Book.
 REI Classed 100A1
 Survey, No. 25824 Port Juan
 S. OR EXAMINATION AS PER RULE SSK01
 Cause of Repairs to be clearly stated.

*actom painted. Rudder pintles broken. ceiling equal to
 18 strakes on each side lifted all fore and aft. cement
 saking. Plonstc Examined and found good. Chain
 plates hanged out. a hand deck pump fitted in fore com-
 partment. Spars Examined*

No. 100A1

Present	Condition of the	Good	Greenails	Rivets	Good	Windlass and Capstan	Good
Decks	Waterways	---	Breasthooks and Stenson	---	---	Pumps 3 No	---
	Comings	---	Transoms, Pointers, and Crutches	---	---	Boats 3 No	---
	Upper Deck Beams & Fastenings	---	Timbers of the Frame at the openings	---	---	Masts, Yards, &c.	---
	Lower Deck Beams & Fastenings	---	Ditto Ditto at other places	---	---	Condition, how ascertained by Exam ⁿ	---
	Stanchions	---	Keelsons	---	---	Sails a few new Good	---
	Top-sides	---	Clamps and Shelves	---	---	Anchors No. of 3 B. 18 + 2 K	---
	Wales	---	Ceiling	---	---	Cables 240 fms Good	---
	Plank	---	Rudder	---	---	Hawsers and Warps 5 No	---
	Wales	---	Copper (on Y.M.)	---	---	Standing & Running Rigging	---
	Plank (Bottom) and Counter	---	Caulking of	---	---	Cargo and Main Hatchways Good	Hatches Good
	Engine Room Skylights	---	Bottom, Deck, & Waterways	Good	---		
		---	Coal Bunker, Openings, Lids, &c.	---	---		
		---	Scuppers	Good	---		

General Observations, Opinion as to Class, &c.
*She is now in good condition, eligible to be continued as
 Classed and marked SS Lm K01. 80*

*James Tierpin
 Willm. B. Davey*

The Amount of Entry Fee ... £ 3 : 3 : 0 received by me,
 to be sent as per margin...
 Certificate (if required)
 Travelling Expenses, if any, £

Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute Friday, November 19th, 1880

Character assigned 100 Bm 1
SS No 1-80



© 2019
 Lloyd's Register
 Foundation