

ANNUAL SURVEYS.

No. 27297 Survey held at Liverpool Date, first Survey 18th Oct. Last Survey 22nd Oct. 1880
 No. in on the Barque "Margaret Heald" Master Williams
 Reg. Book. 301 Tonnage 605 Built at Liverpool When built 1874-2 mo
 By whom built Evans Owners J. B. Fook
 Port belonging to Liverpool Destined Voyage Brisbane
 If Surveyed Afloat or in Dry Dock Clarence Dry Dock.

Last Survey, No. 25274 Port of Iron Classed 100 A.1.
 Present Condition of the Decks Good Trunnails Rivets Good
 Waterways — Breasthooks and Stems —
 Comings — Transoms, Pointers, and Crutches —
 Upper Deck Beams & Fastenings — Timbers of the Frame at the Openings —
 Lower Deck Beams & Fastenings — Ditto ditto at other places —
 Planksheers — Keelsons —
 Sheerstrakes — Clamps and Shelves —
 Topsides — Ceiling —
 Walls — Rudder —
 Plate (Bottom) and Counter — Copper or Y.M. Cement When put on 1877
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. — Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom sighted cleaned and coated with Patent Composition and the topsides with Paint. Vessel in good and efficient condition, and in my opinion eligible to remain as classed.

Committee's Minute Liverpool Nov^r 30th 1880.

Character assigned 100 A.1.

J. W. Blafell.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. ✓ Survey held at Liverpool Date, first Survey 20th Nov. Last Survey 23rd Nov. 1880
 No. in on the Ship "Bay of Bengal" Master M'Cunn
 Reg. Book. 144 Tonnage 1527 Built at Glasgow When built 1875-8 mo
 By whom built Elder Owners J. & J. Bullock
 Port belonging to London Destined Voyage Rangoon
 If Surveyed Afloat or in Dry Dock Princes Dry Dock

Last Survey, No. 2410 Port of Iron Classed 100 A.1.
 Present Condition of the Decks Good Trunnails Rivets Good
 Waterways — Breasthooks and Stems —
 Comings — Transoms, Pointers, and Crutches —
 Upper Deck Beams & Fastenings — Timbers of the Frame at the Openings —
 Lower Deck Beams & Fastenings — Ditto ditto at other places —
 Planksheers — Keelsons —
 Sheerstrakes — Clamps and Shelves —
 Topsides — Ceiling —
 Walls — Rudder —
 Plate (Bottom) and Counter — Copper or Y.M. Cement When put on —
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. — Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom sighted cleaned and coated with Patent Composition and the topsides with Paint. Vessel in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute Liverpool Nov^r 30th 1880

Character assigned 100 A.1.

J. W. Blafell.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

Margaret Heald
Bay of Bengal

27297.



© 2019

Lloyd's Register
Foundation