

REPORT of SURVEY for REPAIRS, &c.

No. *39833*

No. in Survey held at
Reg. Book.

468 on the

TONNAGE under Tonnage Deck
Ditto of Spar Deck, or Awning Deck
Ditto of Poop
Ditto of Raised Qr. Dk.
Ditto of Houses on Deck
Ditto of Forecastle
Gross Tonnage
Crew Space, as per Rule
Register Tonnage, cut on Beam
Engine Room
Reg. Tons as S^rmer, cut on Bm.

Length of Poop

ft. Ditto, Forecastle

ft. Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Last Survey, No.

Port

Classed

100A1

REPAIRS, OR EXAMINATION AS PER RULE

Cause of Repairs to be clearly stated.

Vessel placed in dry dock bottom cleaned and recoated with paint

The Port Bower Anchor & one half of the chain cable was lost.

Certificates have been produced for Anchor & Cable as under
No 5506 Weight of Anchor 36.0.14 Proof strain 33.4.0.7

Mark 120 5.79 L.P.H.T B.54 T.

No 4852 Length 77 7ms 1/2 ft 1 7/8 Stud Link Chain cable

Test 63 1/4 Tons and 88 5/8 Tons

Lipton 29th Sept. 1879 (Signed) Erastus R. Isitt Super^t

No 4533 Length 60 7ms 1 7/8 Stud Link Chain cable

Test 63 1/4 Tons, and 88 5/8 Tons

Lipton 10th Jan. 1880 (Signed) Erastus R. Isitt Super^t

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

Good

Freenails

Rivets

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper (or Y.M.)

Caulking of

Bottom, Deck, & Waterways

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors

Cables

Hawsers and Warps

Standing & Running Rigging

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

The Amount of Entry Fee ...

Special ...

Certificate (if required)

to be sent as per margin...

(Travelling Expenses, if any, £)

Committee's Minute

Character assigned

Friday, November 26th. 1880

R. Williamson

James Curpin

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register
Foundation

We have been assured that the new Anchor & Cable were put on board, but had no opportunity of verifying the same, as no notice was given - as promised - before the vessel had sailed and the Certificates only sent here on the 19th Inst.

James Purpin

28515 Iron



© 2019

Lloyd's Register
Foundation