


28647  
Report of Survey for Repairs of Engines and Boilers.

No. \_\_\_\_\_ (Received at London Office, \_\_\_\_\_) (Rec'd 6.11.80.)  
No. in Reg. Book. Survey held at London Date, first Survey \_\_\_\_\_ and Last Survey Nov. 2<sup>nd</sup> 1880  
8 on the Machinery of the S. S. "Dacia" (Number of Visits 1)  
Tonnage, Gross 1856 Built at Sunderland When built 1867  
Ditto, Net 1473 Owners Ind. Rub. Gut. Pn. & Co. Port belonging to London  
Diameter of Cylinder 23" & 45" Engines made by G. Clark When made 1867  
Length of Stroke 36" Boilers made by \_\_\_\_\_ When made 1875  
Pressure of Steam 70 lbs. If Surveyed Afloat or in Dry Dock \_\_\_\_\_  
Registered Horse Power 170 Years assigned. Character in Register Book. B 1  
Last Survey No. \_\_\_\_\_ Port B + MS. 6.80.

Particulars of Repairs and Examination For Annual Survey  
Vessel placed in dry dock, sea connections ex-  
amined and found in good condition.  
Propeller in good condition. Tail shaft  
a good working fit in Stem Bush.

General Observations, Opinion, and Recommendation:— As far as seen this  
ship appears eligible to remain as classed.

Entry or Registering Fee ... £ : :  
Survey Fee ... £ : : received by me, }  
Certificate (if required) ... £ : : 188 }  
avelling Expenses, if any, £ \_\_\_\_\_

Committee's Minute Tuesday, December, 14<sup>th</sup> 1880.  
Assigned \_\_\_\_\_  
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.  
 Lloyd's Register Foundation