

REPORT of SURVEY for REPAIRS, &c.

(Received at London Office, 18/12/80)

27315
 in Survey held at Liverpool Date, first Survey 10th July Last Survey 21st July 1880
 Book. B.S. "Gadlys" Master English
 on the B.S. "Gadlys" YEAR. MONTH. 1876 6
 TONNAGE under Tonnage Deck 505 Built at Sunderland When built 1876
 Ditto of Spar Deck, or Awaiting Deck Owners J. Prust. Port belonging to Swansea
 Ditto of Poop Residence Swansea
 Ditto of Raised Qr. Dk. By whom built Birrell Destined Voyage Valparaiso
 Ditto of Houses on Deck If Surveyed Afloat or in Dry Dock Dandon Dry Dock
 Ditto of Forecastle (State Name of Dock)
 Gross Tonnage 545
 Crew Space, as per Rule 500
 Register Tonnage, cut on Beam
 Engine Room
 Reg. Tons as Stmer, cut on Bm.
 Length of Poop ft. Ditto, Forecastle 21 ft. Ditto, Raised Quarter Deck 33 ft. Years assigned. Character in Register Book.
 Classed 100 A.1.
 Last Survey, No. 21503 Port Iron 8-78

REPAIRS, OR EXAMINATION AS PER RULE
 Cause of Repairs to be clearly stated.

Part I. I. No 1.

Bottom examined, timbers and ceiling in hatches on each side from the collision bulkhead extending forty feet aft, and from the quarter hatch aft tilld. Cement in good condition and firmly adhering to the Iron, bottom coated with Patent Composition and the topsides with Paint.

The remaining portion of the hold; viz - about 40 feet amidships could not be examined being covered with outward bound cargo, but which will be submitted for survey on her return.

Present Condition of the Decks	Good	Treenails	Keels	Good	Windlass and Capstan	Good
Waterways	---	Breasthooks and Stems	---	---	Pumps	---
Comings	---	Transoms, Pointers, and Crutches	---	---	Boats	---
Upper Deck Beams & Fastenings	---	Timbers of the Frame at the openings	---	---	Masts, Yards, &c.	---
Lower Deck Beams & Fastenings	---	Ditto Ditto at other places	---	---	Condition, how ascertained	See &c.
Planksheers	---	Keelsons	---	---	Sails	Good
Sheerstrakes	---	Clamps and Shelves	---	---	Anchors No. of	3 B - 1 S - 2 K.
Topsides	---	Ceiling	---	---	Cables	Good
Wales	---	Rudder	---	---	Hawsers and Warps	Do.
Plank (Bottom) and Counter	---	Copper (or Y.M.)	Cent - When put on	76	Standing & Running Rigging	Do.
Engine Room Skylights	✓	Caulking of Bottom, Deck, & Waterways	Good	---	Scuppers	Good
Coal Punks, Openings, Etc., &c.	✓	General Observations, Opinion as to Class, &c.	Good	---	Cargo and Main Hatchways	Good
Scuppers	Good				Hatches	Good

This vessel when examined is in good and efficient condition, and in my opinion eligible to remain as classed.

The Amount of Entry Fee £ : : received by me, } J.F.L. J.W. Blasell.
 Special £ 2 : 2 : 0 18/12/80 }
 Certificate (if required) }
 to be sent as per margin... } £ : :
 (Travelling Expenses, if any, £)
 Committee's Minute Liverpool Dec 17 1880
 Character assigned 100 A.1



Insert Character precisely as in Register Book.

IRON 497-0334

18/1/81

Gadlys

27315



© 2019

Lloyd's Register
Foundation