

with report - 2487

Midship Section of No 112 S.S.

Scale $\frac{1}{2}$ = 1 foot S.S. "SADO"

To have diagonal tie plates on Beams as per Rule

Stringer plate on ends of Beams should be $\frac{9}{16}$ for half length amidships as per Rule for excess in length, in line of $\frac{1}{16}$. JH

10/2/66
J.H.



IRON 499-0278