

No. 104 in Register Bk

# IRON SHIPS.

Recd. 4/10/69

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18

on the Screw Steamer "Viceroy" Master \_\_\_\_\_

Tonnage under Tonnage Deck 908.52

Ditto of Spar Deck, or Awning Deck \_\_\_\_\_

Ditto of Poop, or Raised Qr. Dk. 143.84

Ditto of Houses on Deck \_\_\_\_\_

Ditto of Forecastle Excess of .47

Gross Tonnage 1052.83

Crew Space, as per Rule \_\_\_\_\_

Register Tonnage, cut on Beam \_\_\_\_\_

Engine Room \_\_\_\_\_

Register Tonnage, as a Steamer, }  
cut on the Beam .....


Built at Sunderland When built 1862 Launched \_\_\_\_\_

By whom built Oswald Owners Bailey & Co

Port belonging to Hull Destined Voyage \_\_\_\_\_

If Surveyed while Building, Afloat, or in Dry Dock \_\_\_\_\_

Appreciate Tonnage  
When lengthened



© 2021

Lloyd's Register  
Foundation

IRON502 - 0100