

Lloyd's Surveyors' Office.

Hull 2<sup>nd</sup> Octbr 1869

Sir

Herewith are enclosed Birdship sections & particulars of approximate tonnage of the Iron Steamer "Fieroy" with copy of letter received from the Builders who are now lengthening the vessel - The thickness of the Intercostal Ribbed Plate is not given though not being yet able to measure the same -

The size of Frames on the report are  $4\frac{1}{2} \times 3\frac{1}{8}$  the Builders have entered  $4\frac{1}{4} \times 3 \times 7.6$  and which I imagine arises from a difficulty to obtain the other size of angle iron

I am

Yours Obed<sup>t</sup> Servant

Geo B Siffert Esq<sup>r</sup>  
London



Wm Davidson

Lloyd's Register  
Foundation

1200502-0101