

S.S. Benton Report No 12.192.

Hatch is fitted in ship.

Hatch

Loss Beam

S. S. Benton.

Arrangement of Keelsons etc, in new part.

Scale $\frac{1}{4}$ " = 1 Foot.

April 26th 1919.

now added

plate attaching Beam to Hold stringer plate

Inset plate

Two angles and face plate

Elevation

Rec 1/3/19
RB



Engine room St.

Boiler room St.

Wash Plate

Intercostal Keelson Plate 19 x 7/16
Connected to shell plating

Intercostal Keelson plate 19 x 7/16
connected to shell plating

Side of ship

Plan

Intercostal Keelson to be fitted at upper turn of Bilge for 19'-0"

7 x 7/16 plate fitted to lower bilge Keelson for 6'-6"

Bilge Keelson
Tank Girder.

Engine Room Bulkhead

Engine Bearer

Engine Room Bulkhead

Engine Bearer

Engine Bearer

Centre Keelson

Wash Plates

Intercostal Keelson scarping Engine seats & Tank Girder.

Centre Keelson

Tank Girder

Centre Girder

Tank Girder

Tank Girder
Bilge Keelson

Side of ship

1/3/19



© 2021

Lloyd's Register
Foundation

IRONS-0239