

1st ENTRY REPORT.

29/6/74

Ans^d 29/6/74.

S. S. "Black Watch"

It is submitted that this report be returned to Mr. Bonniwell for him to correct the requirements of the Rules as regards the thickness of the main deck stringer plate, and to state whether the thickness is in accordance with the rules or not. and he should be requested to show what thicknesses ^{of plating} apply to the midship portion of the vessel and what thicknesses at the ends.

Letter as above
29/6/74.

29/6/74

J. M.
R. J.

© 2021

Lloyd's Register
Foundation

IRON509-0040