

Litz Renter -

Say in addition to Mr Martells remarks - that the Committee think it right to draw the Owners attention to the fact that the Chain Cables are much too small for a vessel of her size, and altho they cannot in consequence design the Figure 1 - they are surprised the Owners should have risked the ~~refraining~~ ^{refraining} safety with sending the vessel away with insufficient cables.

IRONSIO-0050

Lloyd's Register
Foundation

Pi
-351215-