

Ship "Bann" Report No. 11.194. Exand No. 147

Sections of Topmasts (of iron.)

No. 14788


See Sunderland Surveyor's Letter 8/10/1875.

Recd 9/11/75

Fore & main Topmasts


Mizen Topmast

Diar at heel 20"
" " head 16 1/4
length ex. 49' 5"



plating at heel 5/16
" " head 1/16

Diar at heel 18 1/4
" " head 14 1/2
length ex 44' 0"




plating at heel 5/16
" " head 1/16

Note the seams of plating to Butt on
the Tee bars. Bolts of plating
~~double~~ rivetted

T. R. Oswald
Pallion
Sunderland

*Double-plating has been fitted in way of Lower Mast
Caps. and the said Topmast are especially well
fortified in way of the Rib and Shear. holes.*

*S. Williams
24th Aug. 1875.*



© 2021
Lloyd's Register
Foundation

IRON 512-0135

18/11/75