

## Iron Snow "Premier"

It is submitted that Mr. Ashton should be requested to state for the information of the Committee whether the outside plating was bored in order to determine the actual thicknesses, as it does not appear from his Report that this has been done. And if not Mr. Ashton should give his reasons for not having this done in this instance.

J. H. P.  
12/4/46. R.

*[Signature]*



© 2021

Lloyd's Register  
Foundation