

Lloyd's Register of British & Foreign Shipping.

Greenock, Nov. 23<sup>rd</sup> 1875

Sir  
Herewith I beg to forward Report  
on Engines & Boilers of the S.S. "Leeds"  
(Glasgow Report No. 4137) and beg to  
draw attention to the Tunnel not  
being watertight and no door fitted  
on Bulkhead. The Messrs. Inglis  
who repaired the vessel stated that  
these requirements formed no part  
of their contract, and would be  
attended to by the Owners at "Grimsby"  
where all extras were to be completed.

The Secretary  
Lloyd's Registry  
London

I am Sir  
Your Obedient Servant  
James Morrison



© 2021

Lloyd's Register  
Foundation



24/10/75

Mr Parker Trenchard

B.M.  
2



© 2021

Lloyd's Register  
Foundation