

Letter received from Mr. Tyrrell with reference to the record in the Register Book of the moulded depth of the screw steamer Lizzie English.

The owners of this vessel, Messrs Pyman Bros., having called attention to recorded moulded depth ~~of this vessel~~ as being obviously incorrect, Mr. Tyrrell was called upon to explain the apparent discrepancy. Mr. Tyrrell, after the lapse of so long a time, is not able to make any explanation, but the figures recorded in the Register Book, appear, when compared with the registered depth, to be inaccurate to the extent of some inches, and it is submitted that until the exact depth has been ascertained by remeasurement, that now recorded in the Book should be expunged. Mr. Tyrrell should also, it is submitted, be desired to exercise greater care in the measurement of vessels in future, as such errors are liable, as pointed out by the Marine Superintendent for the owners, to cause those persons some injury.

Ln. 29.7.

Ans. 4.8

(Mr. & Cff)

& Memo to H.P.S.

J.H.

4/8/86

P.J.

W.W.



© 2021

Lloyd's Register
Foundation

1R0N542-0174