

Foothooks	4	—	4	4	4	Garboard to Bilge ..	2½	2½	Timber Strake ..	—
Ditto	4	—	4½	4½	4½	Bilge Planks	2½	2½	Bilge Planks ..	—
									Ceiling in Flat ..	—

Jersey 4th August 1864

H. W. Bonnell Esq
 Lloyd's Surveyors
 Southampton

Sir,

We are in receipt of your favor 2nd inst informing us
 that it is not stated in the report of the "Prairie Flower"
 whether she has diagonal plates

In reply we beg to say that section 39 about the
 she has been quite overlooked by us, and we notice to
 be within the rules the vessel should have been 3 to 4 in
 her

We however hope that the "Prairie Flower" will not
 be prevented from being classed through this oversight
 we have placed additional to the rules 8 Long Hanging
 knees & Lodging Knees between every Beam.

Mr. Tyrell requested us to forward the certificates of testing
 chain & anchors we have therefore forwarded them saying
 you will please observe there has been a anchor replaced
 one in Report is 8 cwt. and this 9 cwt. - when furnishing
 same you will oblige by returning them

We Remain Dear Sir


Yours Respectfully
 J. M. Talbot
 J. M. Talbot Esq



© 2019

Lloyd's Register
 Foundation

SER549-0332



J. W. Bonniwell Esq
Lloyds Surveyor
Southampton.



© 2019

Lloyd's Register
Foundation