

514
28

Bellus

Builder's Name

Surveyor's Name

Masts, Yards, &c.

Sails.

2 lbs 4 ozs. Gallant Sail and
found in other sails

Cables, Cordage, &c.

} all gone

Anchors.

Boats.

Owner's Name

© 2019

Lloyd's Register
Foundation

61V572-0127

SURVEYOR'S REMARKS.

Timbering. *British & African both good dimensions quality squaring*
The Quality, and workmanship
Squaring, and *Windsor & White both body 15 ft with a rising Chalk.*
Workmanship. *2 lead pans with copper chambers.*

Planking. *as specified good quality edging 2 between 4 & 5 & 2 between*
Outside and Inside & 2 & 3 & 2 between for some timber
Quality, Edging,
and Workmanship. *Ceiling British & Home Danyig oak in bays of flat good quality*
well worked

Fastenings. *Copper fastened — wood bolging knees. & 13 pair of Iron hanging*
If Sheathed, *knees under deck. — wood bolging knees stringer*
Doubled, or *about lower hold beams 3 1/2 x 10 of African Oak well fitted*
Felted. *& bolted full 3 parts of the nails through & wedged*
Sheathed with copper

Repairs.

General Observations *A well built vessel — good materials — well fastened — well found*
and Opinion as *in very good order — fit to carry any general cargo with*
required by the *perfect safety and in my opinion entitled to be classed H.A.*
Instructions.

Wm. Harrison

The Amount of the Fee, £ 1 : 1 : 0 is received by me.

Committee Minute *21 February 1835*

Character assigned *A 1 for 10 years*

Wm. Harrison



© 20
 Lloyd's Register
 Foundation

Wm. Harrison, 1835