

6108

Liverpool 27 May 1844

Charles Graham Esq

Sir

I beg to inform you that in the case of the Barge "Bank" the second and third Futtocks, as also the Toptimbers were found to be slackmated by several listings having been "originally left out all fore and aft" not only at the Futtock heads as required by the Rules but also at the Futtock heels. The Rule in this case in this Port has always been most strictly attended to but I was not aware that it was necessary to state in our Reports that it had been done.



© 2019

Lloyd's Register
Foundation

LIV577-0320