

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19 Dec 1906 When handed in at Local Office 20 DEC 1906 Port of LIVERPOOL

No. in Reg. Book 209 on the Food, Iron or Steel BK. "LORD ELGIN" Master H. Howden

Survey held at Ellerman's Quay & Liverpool Date, First Survey 13 Nov 1906 Last Survey 18 Dec 1906

Built at Belfast By whom Workman, Clark & Co. Ltd. When 1891-8

Owners' Address Owners' Address (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Both Name of Dock Ellerman's & Sulthouse Destined Voyage Port Natal

WB=CellDBorDBa feet; uE&B feet; f feet; total capacity tons. FPT tons; APT tons; MT feet tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report, No. 7478 Port Brs

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition

Work done: Vessel examined on pontoon, rudder lifted and re-bushed. Bottom cleaned and coated.

| SUMMARY OF DAMAGE REPAIRS :- | Plates. | Frames. | E. Frames. | Floors. | Beams. | Str. Plates. | Dk. Plates. | Other Items :- |
|--------------------------------|---------|---------|------------|---------|--------|--------------|-------------|----------------|
| Renewed | | | | | | | | |
| Removed and Faired or Repaired | | | | | | | | |
| Faired or Repaired in place | | | | | | | | |

| PRESENT CONDITION OF THE | Stringers | Dblg. Plates under Sounding Pipes | Copper, or Y.M. of Wood Vessels |
|--------------------------|---------------|--------------------------------------|---------------------------------|
| Decks | good when run | | (State if on Felt.) |
| Caulking of Decks | | Engine Room Skylights | When put on, Month Year |
| Waterways | | Coal Bunkers, Open'gs, Lids, &c. | Boats |
| Coamings | | Scuppers | Masts, Yards, &c. |
| Beams & Fastenings | | Cargo Hatchways | Condition, how ascertained |
| Outside Plating | | Hatches | (State if wedges removed) |
| Caulking of ditto | | Planking of Wood Vessels | Sails |
| Rivets | | Caulking ditto | Equipment letter |
| Breasthooks & Crutches | | Treenails ditto | Anchors, No. of |
| Transoms | | Breasthooks & Stems ditto | Cables (State if now ranged) |
| Frames | good when run | Transoms, Pointers, & Crutches ditto | " length |
| Reverse Frames | | Timbers of Frames at openings ditto | " Rule length |
| Floors | | Ditto ditto at other places ditto | Hawsers & Warps |
| Keelsons | | Stringers, Clamps & Shelves ditto | Standing & Running Rigging |

General Observations, Opinion as to Class, Recommendation, &c. :-

This vessel is, so far as run, in good and efficient condition and eligible, in my opinion, to remain as classed and to have record of 12.06

Survey Fee (per Section 28) Special Damage or Repair Fee (if any) Travelling Expenses (if chargeable) Second Surveyor's Fee (if any)

Committee's Minute LIVERPOOL 21 DEC 1906

Character Assigned 100 A1 record 12.06

Has a Survey also been held on the Machinery of the ship? If so, is the Report sent now, or when will it be sent?

No Certificate required if so, to be sent to

