

119

REPORT of SURVEY for REPAIRS.

No. 1791 Port of London Date Sept^r 19 1835
 Survey of the Bark Nestitt Master Simpson
 Tonnage 245 By whom built Young Where built London
 When built 1800 Owners Nichols & Co Port belonging to London
 Destined Voyage Jamaica
 Surveyed Afloat or in Dry Dock Dry Dock

Original Survey, No. 699 Dated October 1834 Class'd A.1
 Port London

Repairs.

At the present time Copied Examined and repaired when necessary - The Side Stern Timbers Scarphed and the After Ends of the Topsides properly shifted over them, New Quarter pieces - Ends of Deck listed Hood Hook on Deck removed and replaced by a long Iron Breast Hook extending aft to the Catheads

General Observations and Opinion, as required by the Instructions.

The Copper of this Vessel is in good and efficient Condition - The Timbers aloft seen in shifting Stern Timbers are sound and in good condition The Topsides, Traces, Waterways Planksheers Decks, Waterways Deck fastenings, Breast Hooks Transoms & Comings are in good condition In my opinion she ought to remain class'd A.1
 George Bayley

The Amount of Fee £ 1 : 1 : - is received by me. *[Signature]*

Committee Minute 22 Sept 1835

Character assigned Continue Class A.1
[Signatures]

