

1856

REPORT of SURVEY for REPAIRS.

No. 1856 Port of London Date Oct^r 14 1835
 Survey of the Cash Call Argos Master Lawrence
 Tonnage 304 By whom built _____ Where built Shields
 When built 1829 Owners Argos & Co Port belonging to London
 Destined Voyage Honduras
 Surveyed Afloat or in Dry Dock Dry Dock

Original Survey, No. 620 Dated Sept^r 1834 Clapd 1041
 Port London

Repairs.

At the present time caulked from the keel up to the wood sheathing of the upper course - The braces, Topsides, Planksheers, Waterway beam and Quarter caulked - Part of the wood sheathing taken off under the Quarter and replaced with new - The wood sheathing caulked - The Planksheer Rail shifted in way of the Loops - Timber (seams) in good condition - Additional fastening put into the Planksheer, and generally overhauled - Felted and Copied at the present time

General Observations and Opinion, as required by the Instructions.

The general appearance of this vessel is favorable throughout - The charts, sails & stores are efficient and sufficient in quantity

George Bayley

The Amount of Fee..... £ 2 : 2 : 0 is received by me. *W. H.*

Committee Minute 20 October 1835

Character assigned Record Repairs Seantime Clapd



© 2019

Lloyd's Register
Foundation

LON 598-0166