

1872

REPORT of SURVEY for REPAIRS.

No. 1872 Port of London Date Oct 7-10 1835
 Survey of the Ship West Indian Master McArthur
 Tonnage 328 By whom built Hillhouse Where built Droitot
 When built 1829 Owners Boddrington & Co Port belonging to London
 Destined Voyage St Vincent
 Surveyed Afloat or in Dry Dock Dry Dock

Original Survey, No. 100 Dated May 1834 Chap. 10A1
 Port London

Repairs.

At the present time Caulked from the keel to the
 Mole - the Bottom thoroughly overhauled and the
 Bottom recoppered several Keenails of upper course
 shifted and several pieces in the planks abut
 at about the Light water mark -

At some not very distant period the upper course
 of this vessel has been extensively shifted with
 a species of African Oak of yellow colour -

General Observations and Opinion, as required by the Instructions

This vessel has been in severe weather during
 the voyage - does not show any appearance of
 working or straining at the Waterway seams or
 Break of the Deck. The Bottom is in good ^{condition} ~~condition~~
 generally & has stood the caulking well at the
 present time - Requires to be closely watched

George Bayley

The Amount of Fee.....£ 2 : 2 : 0 is received by me. H. H.

Committee Minute 20 October 1835

Character assigned Record Repairs / Continue Chap. 10A1



© 2019

Lloyd's Register
 Foundation

LON 598-0184