

REPORT of SURVEY for REPAIRS.

1880

No. 1000 Port of London Date Oct 17 1835
 Survey of the Ship Black River Packet Master Baker
 Tonnage 265 By whom built _____ Where built Southampton
 When built 1825 Owners M. Monico Port belonging to London
 Destined Voyage Jamaica
 Surveyed Afloat or in Dry Dock Dry Dock

Original Survey, No. 864 Dated May 1834 Classed 10A1
 Port London

Repairs. At the present time - has been caulked from the keel to the sheathing - the blocks taken out and the keel seam caulked - lifting out under the trale and seam caulked together with the bolts in the stake below the trale - New bowsprit Beam & and an additional Breast block fitted & reoppered. -

General Observations and Opinion, as required by the Instructions.

This ship is now in an efficient state of repair - does not ~~not~~ give any indication of working aloft - Her sails, stores are in good & efficient condition, & she is in my opinion ~~right~~ correctly classed 10A1

George Bayley

The Amount of Fee..... £ 1 : 1 : 0 is received by me. at the Office

Committee Minute 23 October 1835

Character assigned Record Coppering & continue Class
10A1

Monico & Mary & Co



© 2019

Lloyd's Register
 Foundation

LON 578-0192