

2038

Annual
REPORT of SURVEY for REPAIRS.

No. 2038 Survey held at London Date 4th Dec^r 1835
361
on the Sch^r Charles Carter Master Christal
Tonnage 175 Built at Shouham When built 1833
By whom built _____ Owners Christal Sen^r
Port belonging to London Destined Voyage Africa
If Surveyed Afloat or in Dry Dock _____

Original Survey, No. 1067 Dated January 1835 Classed 11 A1
Port London

Repairs. At the present time 5 new Stanchions which had been broken from the strain produced by the fore rigging the dead eyes of which were attached to the masts and formed a great angle with the ship's side

General Observations The Hull of this vessel appears sound in every respect
and Opinion, as port to working at the beam ends the stows are
required by the good and sufficient The Masts Rigging Sails
Instructions. all sufficient and good.
In my opinion may be returned
under present Class 11 A1

Christal

The Amount of Fee..... £..... is received by me.

Committee Minute 11 December 1835

Character assigned Continue Class 11 A1
M.H.



© 2019
Lloyd's Register
Foundation
LON 598-0369