

If Surveyed Afloat or in Dry Dock Dry Dock

Hold Beam	1 ³ / ₁₆
<i>Gun Deck</i>	1 ¹ / ₁₆
Deck Beam	1 ¹ / ₁₆
same in Iron above the Copper }	

and are ~~apparently~~ free from all defects.

The Deck and Hold Beams are composed of English Oak

The Planking is wrought *Three* — between

General Quality of Workmanship

Surveyor's Name

Jan 20 63

Her Masts, Yards, &c. are in good condition, and sufficient in size and length.

She has SAILS.

CABLES, &c.

ANCHORS.

N ^o .		Fathoms.		Inches.	N ^o .
3	Fore Sails,	300	Chain	2	4
3	Fore Top Sails,	90	Hemp Stream Cable	1 1/4	1
3	Fore Topmast Stay Sails,	100	Hawser	10 1/2	2
2	Main Sails,	100	Towlines	7 1/2	
3	Main Top Sails,	100	Warp	5 1/2	
and <u>will found in small sails</u>		All of <u>good</u> quality.			

Her Standing and Running Rigging is hemp sufficient in size and good in quality.

She has One Long Boat and two quarter boats & jolly boat

The present state of the Windlass is in Capstan good and Rudder good 5 Pumps Copper
Middleton

General Remarks—Statement and Date of Repairs.

Has had at some former period 3 Pair of 1st Futtock Riders and 4 Pair of additional Floor Riders. Put new Wister Kelsons — The date of these repairs cannot be ascertained —

At the present time has been caulked from the Copper up, Decks, Watertaps and Spiketting —

This ship is built on a Companss foot track and fastened throughout in the usual manner — Has 3 Standards to the Stern Frame on the Orlop Deck — & two Bow Standards on the Gun Deck and 2 pair of Takings forward — 11 Floor Riders in all — Her appearance throughout is very favorable —
George Bayley

If Sheathed, Doubled, or Felted, Doubled. Felted Wood sheathed & Coppered
and Date when last done 1833

And I am of opinion this Vessel should be Classed A G. Bayley

The Amount of the Fee.....£ 3 : 3 : 0 is received by me, [Signature]

Committee Minute 29 December 1835

Character assigned A
[Signature] [Signature]



© 201
Lloyd's Register
Foundation