

2094
JH

REPORT of SURVEY for REPAIRS.

No. ³⁸ Survey held at London Date Jan 4 5 1836
on the Bark Achilles Master Duncan
Tonnage 252 Built at Bristol When built 1820
By whom built _____ Owners H Tindall
Port belonging to London Destined Voyage Mauritius
If Surveyed Afloat or in Dry Dock Dry Dock

Original Survey, No. 234 Dated June 1834 Classed A.1
Port London

Repairs. At the present time - Cheeks and Rails to head refitted
one Plank on Starboard Side in way of fore Rigging and two on
Starboard Side above the Males - Side Stern Timbers scupped
and the short planks in the Topside abaft shifted -
caulked from the Copper up - ~~Copper~~ Yellow Metal
sheathing repaired -

General Observations This ship does not appear to have moved, or
and Opinion, as altered her form since she was diagonally sheathed
required by the in 1834 - The Timbers seen where planks were
Instructions. shifted are square and in good condition -
The Hull and Materials are in good and
efficient condition and in my opinion she
should be continued in the class A.1

George Bayley

The Amount of Fee £ 1 : 1 : 0 is received by me. At the Office

Committee Minute 12 Janry 1836

Character assigned Repaired & Continued Class A.1
Commenced 19 Janry
Fee to be returned if
no repairs to be needed
Atty