

ANNUAL SURVEYS.

2142

No. 1016 Survey held at London Date Jan 4 16 1836
 on the Ship Symmetry Master Riley
 Tonnage 293 Built at Stull When built 1833
 By whom built _____ Owners Chodwick & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dry Dock

Original Survey, No. 823 Port of London March 1835 Classed 10A1

Surveyor is required to state the present Condition of the

| | | |
|-------------------------|--|----------------------------|
| Deck Beams & Fastenings | Breasthooks | Capstan |
| Deck Beams & Fastenings | Transoms | Pumps |
| Deck Beams & Fastenings | Timbers of the Frame | Masts, Yards, &c. |
| Deck Beams & Fastenings | Topsides | Sails |
| Deck Beams & Fastenings | Wales | Cables |
| Deck Beams & Fastenings | Plank and Treenails (Outside to the Water's Edge) | Anchors |
| Deck Beams & Fastenings | Rudder | Standing & Running Rigging |
| Deck Beams & Fastenings | Windlass | |

Observations and Opinion, Ship has now arrived from the Mauritius & there is
no appearance of straining or working discernable in
any part. The timbers are well squared - they well secured at
and both Decks. She appears to be fully entitled to 10A1 & in my
opinion would have recommended 11A had there been such a clap at
the time she appears to have been originally surveyed.

Committee Minute 26 January 1836
 Character assigned Continue Claps 11A George Bayley

Comm. Min. 18 Mar 1836
to be raised to 11A

Comm. Min. 23 Dec 1834. Refers to until next Meeting.
 Raised to 11A.
 22 Jan 1836

No. 612 Survey held at London Date Jan 4 19 1836
 on the Brig Prowler Master Mcormick
 Tonnage 409 Built at Maryport When built 1830
 By whom built _____ Owners Tomlinson
 Port belonging to Liverpool Destined Voyage _____
 If Surveyed Afloat or in Dry Dock On the Trays

Original Survey, No. 429 Port of Liverpool Decr 1834 Classed 8A1

Surveyor is required to state the present Condition of the

| | | |
|-------------------------|--|----------------------------|
| Deck Beams & Fastenings | Breasthooks | Capstan |
| Deck Beams & Fastenings | Transoms | Pumps |
| Deck Beams & Fastenings | Timbers of the Frame | Masts, Yards, &c. |
| Deck Beams & Fastenings | Topsides | Sails |
| Deck Beams & Fastenings | Wales | Cables |
| Deck Beams & Fastenings | Plank & Treenails (Outside to the Water's Edge) | Anchors |
| Deck Beams & Fastenings | Rudder | Standing & Running Rigging |
| Deck Beams & Fastenings | Windlass | |

Observations and Opinion, Copper examined in fair condition and repaired
when necessary - She appears to be entitled to
remain in her present claps

Committee Minute 22 January 1836

Character assigned Continue Claps 8A George Bayley



© 2019

Lloyd's Register
 Foundation