

ANNUAL SURVEYS.

2300
JH

No. 2300 Survey held at London Date March 1st 1836
 on the Brig Fair Ellen Master Thos. Storks
 Tonnage 215 Built at Newcastle When built 1816
 By whom built _____ Owners W. Bourne
 Port belonging to Portsmouth Destined Voyage Gottenburgh
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 89 Port of London 1834 Classed A.1

The Surveyor is required to state the present Condition of the

Decks <u>Indifferent</u>	Breasthooks <u>Sound</u>	Capstan _____
Upper Deck Beams & Fastenings <u>Good & Firm</u>	Transoms _____	Pumps <u>Appear good</u>
Lower Deck Beams & Fastenings <u>ditto</u>	Timbers of the Frame <u>Wholesome sound</u>	Masts, Yards, &c. <u>ditto</u>
Spirkettling _____	Topsides _____	Sails <u>Well found</u>
Plank Shears _____	Wales _____	Cables <u>ditto</u>
Waterways <u>Good</u>	Plank and Treenails <u>Good</u>	Anchors <u>Two bows & 1 stream & male</u>
Hatchway Comings _____	(Outside to the Water's Edge)	Standing & Running Rigging <u>Good</u>
	Rudder _____	
	Windlass _____	

General Observations and Opinion,
as required by the Instructions,

The decks of this vessel are but indifferent but tight, the hullson very satisfactory but sound, I am of opinion is still fit for the safe conveyance of dry & perishable cargoes and may continue her class A. 2

Committee Minute 18 March 1836

Character assigned To be reduced to F. 2

Notes given: _____

Middleton

No. 350 Survey held at London Date March 7th 18____
 on the Bk Topaz Master S. W. Hurry
 Tonnage 246 Built at _____ When built Warrmouth 1824
 By whom built _____ Owners Wm Martin
 Port belonging to London Destined Voyage Antigua
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 159 Port of London 1834 Classed "A. 1"

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u>Good</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>Firm & sound</u>	Transoms <u>ditto</u>	Pumps <u>ditto</u>
Lower Deck Beams & Fastenings <u>ditto</u>	Timbers of the Frame <u>sound when seen</u>	Masts, Yards, &c. <u>ditto</u>
Spirkettling <u>ditto</u>	Topsides _____	Sails <u>Well found</u>
Plank Shears <u>ditto</u>	Wales _____	Cables <u>ditto</u>
Waterways <u>ditto</u>	Plank & Treenails <u>In good condition</u>	Anchors <u>ditto</u>
Hatchway Comings <u>ditto</u>	(Outside to the Water's Edge)	Standing & Running Rigging <u>Good</u>
	Rudder _____	
	Windlass _____	

General Observations and Opinion,
as required by the Instructions,

This vessel has been in the dry dock bottom examined & repaired, appearance generally favorable, I am of opinion she may continue her present class

Committee Minute 18 March 1836

Character assigned Continue Class B. 1

Notes given: _____

Middleton



© 2019

Lloyd's Register
Foundation

10599-0064