

# ANNUAL SURVEYS.

No. 239 Survey held at London Date March 15<sup>th</sup> 1836  
 on the Ship Lucetta Master Muirhead  
 Tonnage 372 Built at Southwick When built 1828  
 By whom built \_\_\_\_\_ Owners Hall & Co  
 Port belonging to London Destined Voyage Denmark  
 If Surveyed Afloat or in Dry Dock Mess<sup>rs</sup> Pelcher Dry Dock

Original Survey, No. 1736 Port of London Sept<sup>r</sup> 1835 Classed 10A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	

General Observations and Opinion,  
as required by the Instructions,

*at the present time Copper examined and repaired  
where necessary. In my opinion she is correctly  
classed 10A1*

*George Bayley*

Committee Minute 12 April 1836

Character assigned Continue Class 10A1  
*J.W.L. S.B.*

No. Supp. Survey held at London Date March 17 1836  
 on the Schooner Otter Master Dutton  
 Tonnage 176 Built at Shucham When built 1835  
 By whom built S.B. Bally Owners Hanson & Co  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock On Fountain Dockways

Original Survey, No. 14 Port of Shucham July 1835 Classed 12A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank & Treenails (Outside to the Water's Edge)	Anchors
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	

General Observations and Opinion,  
as required by the Instructions,

*at the present time in consequence of having been on  
the ground 12 keel plates replaced and the copper repaired  
there is no appearance of staining visible on the copper  
nor of her having sustained any injury to affect her class -*

Committee Minute 12 April 1836

Character assigned Continue Class 12A1  
*J.W.L. S.B.*

*George Bayley*

© 2019

Lloyd's Register  
Foundation