

REPORT of SURVEY for REPAIRS.

No. 2415 Survey held at London Date March 28 1836
 on the Bar William Bryan Master Roman
 Tonnage 312 Built at Louthampton When built 1816
 By whom built _____ Owners Robt H Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Messrs Lushings Dry Dock

Original Survey, No. 703 Dated 1834. E. 1
 Port London

Repairs. *At the present time caulking from the keel up, fitted. Woodwork &c coppered and generally overhauled—*

The Surveyor to state the present Condition of

Upper Deck Fastenings _____
 Spirketting _____
 Plank Shears _____
 Topsides _____
 Upper Deck with its Appendages _____
 Lower Deck Fastenings _____

Wales _____
 Counter _____
 Plank and Treenails _____
 (Outside to the Water's Edge)
 Rudder _____
 Windlass _____
 Capstan _____

General Observations and Opinion,
 as required by the Instructions,


The general appearance of this ship is very favorable throughout and in my opinion should remain classed F. 1

George Bayley

The Amount of Fee..... £ 2: 2: 0 is received by me. *MC*

Committee Minute 19 April 1836

Character assigned Richd Copper & continue class F. 1



© 2019

Lloyd's Register Foundation

5810-665 No 1