

*REPORT of SURVEY for REPAIRS.*

No. 2580 Survey held at London Date 11<sup>th</sup> June 1836  
on the <sup>135</sup>Bk Bengal Merchant Master Campbell  
Tonnage 503 Built at Calcutta When built 1802  
By whom built \_\_\_\_\_ Owners Hornes  
Port belonging to London Destined Voyage N. S. Indies  
If Surveyed Afloat or in Dry Dock Blackhuts Dock

Original Survey, No. 755 Dated 1884 Classed A-1  
Port London

**Repairs.** At the present time our gride bottom caulked  
generally overhauled and repaired.

*The Surveyor to state the present Condition of*

Upper Deck Fastenings

*Spirketting* \_\_\_\_\_

Plank Shears

*Topsides* (M 950 v)

|                                |           |
|--------------------------------|-----------|
| Upper Deck with its Appendages | Condition |
|--------------------------------|-----------|

Lower Deck Fastenings \_\_\_\_\_

*Wales*

Counter \_\_\_\_\_

Plank and Treenails \_\_\_\_\_ *11 1/2*  
(Outside to the Water's Edge)

Rudder Condition

Windlass

Capstan

*General Observations and Opinion,  
as required by the Instructions.*

General Observations and Opinion,  
as required by the Instructions,  
This Ship is in the most efficient State of repair fit for the conveyance of Army & British stores  
Cargoes & in my opinion may be continued  
The Amount of Fee ..... £ 3 : 3 : - is received by me.

The Amount of Fee..... £ 3 : 3 : — is received by me.

Committee Minute 17 June 1836

Character assigned Record Copying Continued Cap. 4

C. F. SEYFANG, PRINTER, FARRINGTON STREET, LONDON.

© 2019

Lloyd's Register  
Foundation

CONF-99-0353