

REPORT of SURVEY for REPAIRS.

No. 2602 Survey held at London Date 30th June 1836
on the 375 St Marguerite & Huntly Master Mottley
Tonnage 563 Built at Aldershot When built 1802
By whom built _____ Owners Chapman
Port belonging to London Destined Voyage Dunkirk
If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 545 1249 Dated 1835 Closed At
Port London

Repairs. At the present time 2 new cheeks to the head

The Surveyor to state the present Condition of
Upper Deck Fastenings _____
Spirkelting _____
Plank Shears _____
Topsides _____ In the best
Upper Deck with its Appendages _____ condition
Lower Deck Fastenings _____

Wales _____
Counter _____
Plank and Treenails _____
(Outside to the Water's Edge)
Rudder _____ In good condition
Windlass _____
Capstan _____

General Observations and Opinion, The existing Planking Fastenings are
as required by the Instructions, all in good condition the ship in the
most efficient state in hull & is fit for the conveyance
of dry & perishable cargo & in my opinion should be
continued as is
The Amount of Fee..... £ : : is received by me. Montgomery

Committee Minute 30 June 1836

Character assigned Continued Class B, 1st
W. H. L.