

REPORT of SURVEY for REPAIRS.

No. 2634 Survey held at London Date 11th July 1836
 on the Ship Boxborough Master Chapman
 Tonnage 757 Built at London When built 1812
 By whom built Atcher Owners Chapman
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 46 Dated 1834 - Classed EA
 Port London

Repairs. At the present time, new Plank in the Counter ~~the~~
 additional bolting in bullock Plank & sides of water the
 main deck & the small part of waterway new lower deck
 beam clamped, small piece of Plank in topsides.
 See annexed Survey

The Surveyor to state the present Condition of

Upper Deck Fastenings _____
 Spirketting _____
 Plank Shears _____ In good
 Topsides _____ condition
 Upper Deck with its Appendages _____
 Lower Deck Fastenings _____

Wales _____
 Counter _____
 Plank and Treenails _____
 (Outside to the Water's Edge.)
 Rudder _____ In good condition
 Windlass _____
 Capstan _____

General Observations and Opinion,
 as required by the Instructions,

This ship appears in good sound condition
fastenings firm has been generally overhauled
and repaired as above may in my opinion be continued
as ordered

The Amount of Fee.....£ 5 : 3 : 0 is received by me [Signature]

Committee Minute 15 July 1836

Character assigned Record Repairs Continue