

REPORT of SURVEY for REPAIRS.

No. 2669 Survey held at London Date June 1836
 on the M. Houghton Master Thompson
 Tonnage 282 Built at Shields When built 1826
 By whom built London Owners L. P. H.
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Blackwall Dock

Original Survey, No. 1087 Dated 1834 Closed Yes
 Port India

Repairs. At the present time Copper stripped the bottom
 Caulked, Several pieces put in outside planking,
 Some new nails shifted a pair of iron hanging bars
 put in. wales topsides caulked, bottom filled
 and recoppered therefore must have new
 Riggings

The Surveyor to state the present Condition of

Upper Deck Fastenings _____
 Spirketting _____
 Plank Shears _____
 Topsides _____
 Upper Deck with its Appendages _____
 Lower Deck Fastenings _____

Wales _____
 Counter _____
 Plank and Treenails _____
 (Outside to the Water's Edge)
 Rudder _____
 Windlass _____
 Capstan _____

General Observations and Opinion, The Hull has now been overhauled
 as required by the Instructions, and is in fair condition and for use in
all her fastenings and may in my opinion be
continued her present class till

The Amount of Fee..... £ 1 : 1 : 0 is received by me.

Committee Minute 29 July 1836

Character assigned Repair Repairs & continue Class