

ANNUAL SURVEYS.

2685

No. 2685 Survey held at London Date July 23 1836
 on the Bark Blanche Master Manning
 Tonnage 273 Built at Yarmouth When built 1827
 By whom built _____ Owners Shepherd & Co
 Port belonging to London Destined Voyage India
 If Surveyed Afloat or in Dry Dock Shepherd & Co's Dry Dock

Original Survey, No. 54 Port of London 1834 Classed 10A-1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u>Good</u>	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms <u>Sound</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirkettling _____	Topsides _____	Sails _____
Plank Shears _____	Wales _____	Cables _____
Waterways _____	Plank and Treenails <u>Specimens removed to Dept of Fisheries. (Outside to the Water's Edge) 30.8</u>	Anchors <u>2 of 2 or 3</u>
Hatchway Comings _____	Rudder <u>Good</u>	Standing & Running Rigging _____
	Windlass _____	

General Observations and Opinion, At the present time all the Treenails have been shifted
 as required by the Instructions, from the copper upwards and the upper works overhauled
all in good condition & in my opinion should remain classed
10A-1

Committee Minute 9 August 1836

Character assigned Continue Class 10A-1

George Bayley

No. 202 Survey held at London Date July 27th 1836
 on the Brig William Master Chambers
 Tonnage 134 Built at Calcutta When built 1827
 By whom built _____ Owners Clap
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock On the Brigs

Original Survey, No. 1195 Port of London 1834 Classed 11A-1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u>Good</u>	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps <u>Good</u>
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirkettling _____	Topsides _____	Sails _____
Plank Shears _____	Wales _____	Cables _____
Waterways _____	Plank & Treenails _____	Anchors _____
Hatchway Comings _____	(Outside to the Water's Edge)	Standing & Running Rigging _____
	Rudder _____	
	Windlass _____	

General Observations and Opinion, At the present time copper examined and repaired, this will
 as required by the Instructions, have to be removed at the close of the present year or I apprehend
that by the rules she will be reduced to her class - At present
she is in my opinion eligible to remain in her present class 11A-1

Committee Minute 9 August 1836

Character assigned Continue Class 11A-1

George Bayley



© 2019

Lloyd's Register
Foundation