

2954 Lon

REPORT of SURVEY for REPAIRS.

No. ³⁸⁷ Survey held at London Date Nov-5 1836
 on the Brig Grecian Master Smith
 Tonnage 212 Built at Yarmouth When built 1824
 By whom built _____ Owners J Richardson J Canhile
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Messrs Tebbutt & Lemchile Dock

Original Survey, ~~No.~~ annexed Dated 24th March 1834

Port London

Repairs. At the present time several planks in the Topsides and
 sheer Strakes shifted & curled from the top up
 The Hull generally overhauled

The Surveyor to state the present Condition of

Upper Deck Fastenings _____
 Spirketting _____
 Plank Shears _____
 Topsides _____
 Upper Deck with its Appendages _____
 Lower Deck Fastenings _____

Wales _____
 Counter _____
 Plank and Treenails _____
 (Outside to the Water's Edge.) Good
 Rudder _____
 Windlass _____
 Capstan _____

General Observations and Opinion,
 as required by the Instructions,

The present repairs have in my opinion rendered
 this vessel efficient for the safe conveyance of dry & perishable
 cargoes to any part of the world
George Bayley

The Amount of Fee.....£ 1 : 1 : 0 is received by me. at the Office
1836

Committee Minute 25 November 1836

Character assigned A 1