

REPORT of SURVEY for REPAIRS.

HA

No. _____ Survey held at London Date January 21 1834
 on the Brig Harlequin Master Spurgeon
 Tonnage 190 Built at Yarmouth When built 1834
 By whom built _____ Owners J. Steward
 Port belonging to Yarmouth Destined Voyage Malta & Smyrna
 If Surveyed Afloat or in Dry Dock McRattenburgs Dock

Original Survey, No. 51 Dated 1834 Classed 12 A 1

Port Yarmouth

Repairs.

*At the present time Shipped Caulked from keel
up & recoppered*

The Surveyor to state the present Condition of

Upper Deck Fastenings _____
 Spirketting _____
 Plank Shears _____
 Topsides _____
 Upper Deck with its Appendages _____
 Lower Deck Fastenings _____

Wales _____
 Counter _____
 Plank and Treenails
 (Outside to the Water's Edge) _____
 Rudder _____
 Windlass _____
 Capstan _____

General Observations and Opinion,
 as required by the Instructions,

*Throughout in good condition and
 efficiency — George Bayley*

The Amount of Fee..... £ 1 : 1 : 0 is received by me. at the Office

Committee Minute 27 Jan 1834

Character assigned Class 12 A 1