

REPORT of SURVEY for REPAIRS.

3091

No. 3091 Survey held at Reservoir, London Date January 12 1837
 on the Park Sumatra Master late Richard
 Tonnage 173 Built at Doole When built 1834
 By whom built _____ Owners McAlmout
 Port belonging to London Destined Voyage California
 If Surveyed Afloat or in Dry Dock Gud Dock

Original Survey, No. 137 Dated 1834 Classed 10A1
 Port Liverpool & London No 3083

Repairs. At the present time the ship's bottom caulked throughout some planks in the lower stake of trade shifted on account of its being worn - some shifted under the Quarter Timbers where seen - well squared and of good quality an Iron Hanging or staple standard now put to every Hold Beam - & abutted abaft. Butts & Floor Heads were originally through bolted.

General Observations and Opinion, as required by the Instructions. The materials and workmanship of this vessel are very good - The frame well squared and of good size with the exception of the Pop Timbers which are rather ~~light~~ small the siding way - She is decided superior to ships entitled to be classed 10A by the rules - & in my opinion more eligible to be classed 11A1

George Bayley

The Amount of Fee £ 1 : 1 : 0 is received by me. at the Office See Survey No 3083
 Committee Minute 31 June 1837
 Character assigned raised to A1 per 11 years