

ANNUAL SURVEYS.

3093

No. 3093 Survey held at London

Date Jan^y 24

18 37

on the Ship Albion

Master Pynd

Tonnage 427 Built at Newcastle

When built 1813

By whom built Smith

Owners Hall & Co

Port belonging to London

Destined Voyage Demerara

If Surveyed Afloat or in Dry Dock Messrs Fitchers Dry Dock

Original Survey, No. 358, 114083/82 Port of London

Classed A. 1

The Surveyor is required to state the present Condition of the

Decks

Upper Deck Beams & Fastenings 2 bolts 1837

Lower Deck Beams & Fastenings

Spirketting

Plank Shears

Waterways

Hatchway Comings

Breasthooks

Transoms

Timbers of the Frame

Topsides

Wales

Plank and Treenails
(Outside to the Water's Edge.)

Rudder

Windlass

Capstan

Pumps

Masts, Yards, &c.

Sails

Cables

Anchors No. of

Standing & Running Rigging

Copper

General Observations and Opinion,

as required by the Instructions,

3 Hold Beams

10 New Keels fitted at

upward - are good - A. 1

Committee Minute 31 Janis 183 7

Character assigned Cont. A. 1

The general appearance of this ship is favourable at the present time shifting the counter - timbers

George Bayley

No. 915 Survey held at London

Date 25th Jan

18 37

on the Ship Mormaid

Master J Chapman & Co

Tonnage 473 Built at Calcutta

When built 1817

By whom built

Owners Chapman & Co

Port belonging to London

Destined Voyage Bombay

If Surveyed Afloat or in Dry Dock Simkulu Dock

Original Survey, No. 1583 Port of London

July 1835

Classed A. 1

The Surveyor is required to state the present Condition of the

Decks

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Spirketting

Plank Shears

Waterways

Hatchway Comings

Breasthooks

Transoms

Timbers of the Frame

Topsides

Wales

Plank and Treenails
(Outside to the Water's Edge.)

Rudder

Windlass

Capstan

Pumps

Masts, Yards, &c.

Sails

Cables

Anchors No. of

Standing & Running Rigging

Copper

General Observations and Opinion,

as required by the Instructions,

at present time part new stem lead - piece of plank sheen, Butts of oak & top side caulked - Beam ends braced & generally examined. The condition is good & in my opinion this ship will remain in her present class.

Committee Minute 31 Jan 183 7

Character assigned Continued A. 1

George Bayley