

REPORT of SURVEY for REPAIRS.

3097

No. 307 Survey held at London Date Jan^y 23rd 7 1837
 on the By William Inglis Master Truscott
 Tonnage 140 Built at Yarmouth When built 1820
 By whom built _____ Owners Betty & C. Melhuish Gray & Co.
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock in the Ways & Afloat

Original Survey, No. 37 Dated 1834 Classed "12 A"
 Port Yarmouth

Repairs. All the present time caulked & coppered overboard

The Surveyor to state the present Condition of

Upper Deck Fastenings _____
 Spirketting _____
 Plank Shears _____
 Topsides _____
 Upper Deck with its Appendages _____
 Lower Deck Fastenings _____

Wales _____
 Counter _____
 Plank and Treenails _____
 (Outside to the Water's Edge.)
 Rudder _____
 Winlass _____
 Capstan _____

General Observations and Opinion, Is a strong well built vessel but is generally
as required by the Instructions, shifted two between on the planking

W. Middleton

The Amount of Fee.....£ 1 : 1 : 0 is received by me. at the Office

Committee Minute 25 Feb 1837

Character assigned Class 12 A 1

Referenced to the General Committee