

REPORT of SURVEY for REPAIRS.

No. ²⁶⁹ 3137. Survey held at London Date March 28 1836
 on the Barb Gloucester Master Beckett
 Tonnage 297 Built at Gloucester When built 1833
 By whom built _____ Owners Ustborne & Co
 Port belonging to London Destined Voyage Bordeaux
 If Surveyed Afloat or in Dry Dock Master Helbert & Co's Dry Dock

Original Survey, No. 247 Dated 1834 Classed 12A1
 Port London

Repairs. *At the present time caulked from the keel to the Top of the Copper and recapped - Hullsum caulked*

The Surveyor to state the present Condition of

Upper Deck Fastenings _____	} <u>Good</u>	Wales _____	} <u>Good</u>
Spirkettling _____		Counter _____	
Plank Shears _____		Plank and Treenails (Outside to the Water's Edge) _____	
Topsides _____		Rudder _____	
Upper Deck with its Appendages _____		Windlass _____	
Lower Deck Fastenings _____	Capstan _____		

General Observations and Opinion, *This ship is in an efficient state of repair and in as required by the Instructions, my opinion should remain in her present class*

George Bayley

The Amount of Fee £ 1 : 1 : 0 is received by me. *at the Office*

Committee Minute *See Annual Survey* 1836
Annexed

18 Feb. 1837

Character assigned _____

