

REPORT of SURVEY for REPAIRS.

GH

No. 3170 Survey held at Londra Date 25th Feb 18 37
on the M^{rs} Pirtsea Master James Smith
Tonnage 451 Built at Calcutta When built 1808
By whom built _____ Owners Middle H.
Port belonging to Londra Destined Voyage Cape & Bombay
If Surveyed Afloat or in Dry Dock In dry dock & Afloat

Original Survey, No. 2623 Dated 1836 Closed At
Port Londra

Repairs. At the present time Port her false
keel caulked from the keel up & sheathed with
copper up under the inspection of Mr Bayly - four
new buttones - decks doubled with 2 inch
Gungie deal felled under north and rabbitted
into the waterway

The above repairs were done ~~at~~ under my inspection
in Mr Bayly's Dry Dock George Bayly

The Surveyor to state the present Condition of

Upper Deck Fastenings _____
Spirketting _____
Plank Shears _____
Topsides In good
Upper Deck with its Appendages Condition
Lower Deck Fastenings _____

Wales _____
Counter _____
Plank and Treenails
(Outside to the Water's Edge) _____
Rudder In good
Windlass Salut Condition
Capstan _____

General Observations and Opinion, This ship is now in efficient
as required by the Instructions,
condition both in her Hull and Equipment and may
in my opinion be continued as closed

The Amount of Fee..... £ 2 : 2 : 0 is received by me. at the Office at Bombay

Committee Minute 3 Mar 183 7

Character assigned Capt At 1 accord repairs

Repairs £2.20
paid on 4.0