

REPORT of SURVEY for REPAIRS.

No. 3175 Survey held at London Date Feb 9 25 18 37
on the Schooner Arachne Master Faulkner
Tonnage 148 Built at Fairham When built 1827
By whom built _____ Owners Burrell
Port belonging to Potsmouth Destined Voyage Naples
If Surveyed Afloat or in Dry Dock Fountain Dock

Original Survey, No. 70 Dated 1834 Clapd 10 A1
Port Regency

Repairs. Caulked from keel to trale - Topside caulked
about a month since - Shifting 3 after hours
at the Light Water Mark, originally Beck
Putting through Bolts in all the Butts - and
recapitulating - Shifting the channels

The Surveyor to state the present Condition of

Upper Deck Fastenings _____
Spirketting _____
Plank Shears _____
Topsides _____
Upper Deck with its Appendages _____
Lower Deck Fastenings _____

Wales _____
Counter _____
Plank and Treenails
(Outside to the Water's Edge) _____
Rudder _____
Windlass _____
Capstan _____

General Observations and Opinion, The Timber exposed very good and well
as required by the Instructions, Squared - Her whole appearance very fine
and substantial is fully entitled to her present
Clap. 10 A1
George Bayley

The Amount of Fee £ 10: 6 is received by me. at the Office

Committee Minute 7 March 1837

Character assigned Clap. 10 A1 used repairs & clapped