

REPORT of SURVEY for REPAIRS.

No. 3269 Survey held at London Date 24 June 1836
 on the Charlton Master Robt
 Tonnage 384 Built at Chatham When built 1825
 By whom built — Owners Godwin & Co
 Port belonging to London Destined Voyage India
 If Surveyed Afloat or in Dry Dock At the Dock

Original Survey, No. 583 Dated 1835 Clipped At 1
 Port London

Repairs.

At the present time copper is again caulked
 in the fore and main masts & foremast

The Surveyor to state the present Condition of

Upper Deck Fastenings —
 Spirketting —
 Plank Shears —
 Topsides Good
 Upper Deck with its Appendages Condition
 Lower Deck Fastenings —

Wales —
 Counter —
 Plank and Treenails —
 (Outside to the Water's Edge.)
 Rudder Good
 Windlass Condition
 Capstan —

General Observations and Opinion,
 as required by the Instructions,

This ship continues in good
 condition and may in my opinion
 be continued as before.

The Amount of Fee.....£ Will not Pay is received by me.

Committee Minute 2 April 1837

Character assigned At 1

