

# REPORT of SURVEY for REPAIRS.

No. *3270* Survey held at *London* Date *31 March* 18 *37*  
 on the *William V. Alfred* Master *Wrydale*  
 Tonnage *338* Built at *Sub* When built *1811*  
 By whom built \_\_\_\_\_ Owners *J. Head*  
 Port belonging to *London* Destined Voyage *to America*  
 If Surveyed Afloat or in Dry Dock *Atcliffe Cross Dock*

Original Survey, No. *256, 1588 & 2724* Dated *1816* Closed *At*  
 Port *London*

**Repairs.** *At the present time two planks in the lower stowage and a new Breast Hook*

The Surveyor to state the present Condition of

Upper Deck Fastenings \_\_\_\_\_  
 Spirketting \_\_\_\_\_  
 Plank Shears \_\_\_\_\_ *In good*  
 Topsides \_\_\_\_\_ *condition*  
 Upper Deck with its Appendages \_\_\_\_\_  
 Lower Deck Fastenings \_\_\_\_\_

Wales \_\_\_\_\_  
 Counter \_\_\_\_\_  
 Plank and Treenails \_\_\_\_\_  
 (Outside to the Water's Edge)  
 Rudder \_\_\_\_\_ *In good*  
 Windlass \_\_\_\_\_ *condition*  
 Capstan \_\_\_\_\_

General Observations and Opinion, *The timbers seen in shifting the masts*  
 as required by the Instructions, *proved in very fair condition, the fastenings*  
*are firm and she is in a good state of repair and may*  
*in my opinion be continued as closed* *Ploutenay*

The Amount of Fee ..... £ *10* is received by me.

Committee Minute *J. Head* 183 *7*

Character assigned *Good*

