

ANNUAL SURVEYS.

3286

No. 3286 Survey held at London Date March 28 1837
 on the Bark Prince Master Remond or Reynolds
 Tonnage 391 Built at Wooden Pans When built 1791
 By whom built _____ Owners Chapman & Co
 Port belonging to Whitby Destined Voyage Quebec
 If Surveyed Afloat or in Dry Dock Simkila Wharf

Original Survey, No. 1275, 2687, 6375 Port of London March 1835 Classed E.1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u>Pair</u>	Capstan _____
Upper Deck Beams & Fastenings <u>generally firm</u>	Transoms <u>See</u>	Pumps _____
Lower Deck Beams & Fastenings <u>See</u>	Timbers of the Frame _____	Masts, Yards, &c. <u>Good</u>
Spirketting <u>Good</u>	Topsides <u>Good</u>	Sails <u>2 suits</u>
Plank Shears <u>See</u>	Wales _____	Cables <u>4 or 2 new Hawsons 2 others</u>
Waterways <u>See</u>	Plank and Treenails _____ (Outside to the Water's Edge)	Anchors No. of <u>3 BA 1 SA 2 KA</u>
Hatchway Comings <u>See</u>	Rudder <u>Good</u>	Standing & Running Rigging <u>new fore & main</u>
	Windlass <u>new fitted with Young's Patent</u>	Copper _____

General Observations and Opinion, At the present time many of the Ribs & Sts shifted - her
 as required by the Instructions general appearance is substantial & she is my opinion
eligible to be present Class E.1

Committee Minute 11 April 1837

Character assigned Ant E.1

No. 423 Survey held at London Date March 23rd 1837
 on the Bark Porcupine Master C. Loring
 Tonnage 282 Built at New York When built 1813
 By whom built _____ Owners B. Loring
 Port belonging to Loring Destined Voyage Mauritius
 If Surveyed Afloat or in Dry Dock Afloat in West India Dock by order of Mr Loring

Original Survey, No. 1712 & 3160 Port of London Classed E.1

The Surveyor is required to state the present Condition of the

Decks <u>See</u>	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirketting _____	Topsides _____	Sails _____
Plank Shears _____	Wales _____	Cables _____
Waterways _____	Plank & Treenails _____ (Outside to the Water's Edge)	Anchors No. of _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper _____

General Observations and Opinion, Attended on board by request of Mr Loring and pointed
 as required by the Instructions, out to him the pieces of Plank which are defective
on the underside - April 5th No part of the Plank has
been removed and the keel is now nearly laden - Am still
of opinion that she is not eligible for the safe conveyance
of dry & perishable cargo

Committee Minute 6 April 1837

Character assigned Ant E.1