

ANNUAL SURVEYS.

3290

No. 3290 Survey held at Londra Date April 3^d 18 37
 on the Schooner Master J. Tray
 Tonnage 79 Built at P. B. Island When built 1824
 By whom built _____ Owners Lept
 Port belonging to Londra Destined Voyage Guernsey
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 1464 Port of Londra Classed K1

The Surveyor is required to state the present Condition of the

Decks <u>Not in good condition</u>	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings <u>Not in good condition</u>	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings <u>Not in good condition</u>	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirketting _____	Topsides _____	Sails <u>Main sail not good & the</u>
Plank Shears <u>Not in good condition</u>	Wales <u>Not in good condition</u>	Cables <u>Very fair</u>
Waterways <u>Condition</u>	Plank and Treenails <u>Condition</u> (Outside to the Water's Edge)	Anchors No. of _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper _____

General Observations and Opinion,
as required by the Instructions,

The hull, the ceiling, the decks, waterways & spirketting as well as the Plank Shears & Shear Strakes are in an indifferent condition. She is not fit to take any cargo on a foreign voyage and in my opinion should be valued to £2.

Committee Minute 11 April 1837

Character assigned Edward to I 1 - photos to B. & J. Montney
2.11.37

Change of Property & Master

No. 444 Survey held at Londra Date April 4 18 37
 on the Mr. Thompson Master Thimmils
 Tonnage 282 Built at Shilds When built 1825
 By whom built _____ Owners Coates
 Port belonging to Londra Destined Voyage Dubie
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 1087 & 2669 Port of Londra Classed K1

The Surveyor is required to state the present Condition of the

Decks _____	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings <u>In good condition</u>	Timbers of the Frame <u>In good condition</u>	Masts, Yards, &c. _____
Spirketting _____	Topsides _____	Sails <u>Supper</u>
Plank Shears _____	Wales <u>Condition</u>	Cables <u>&</u>
Waterways _____	Plank & Treenails <u>Condition</u> (Outside to the Water's Edge)	Anchors No. of <u>Good</u>
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper _____

General Observations and Opinion,
as required by the Instructions,

She has now been caulked from the copper up. She and is throughout in good condition and may be continued as cargo.

Committee Minute 11 April 1837

Character assigned Ant. R. 1 second repair
2.11.37

Cook Cook, Lane, Permonsey