

REPORT of SURVEY for REPAIRS.

No. 35 Survey held at LONDON Date 10 Feb 1837
 on the M Warrens Master J Gray
 Tonnage 325 Built at _____ When built _____
 By whom built _____ Owners Mown
 Port belonging to LONDON Destined Voyage South Seas
 If Surveyed Afloat or in Dry Dock at Base

Original Survey, No. Amoy Dated _____

Port _____

Repairs.

See Mr. Bayley's report

Equipment
New Maining & Higgins Mast 100 minutes with Yards &c Complete.
Rigging Part New 100 minutes 200 &c —
Sails Three Sails

3 B. Anchors — Mown & Kedge 225 fathoms Chain Cable
120 do 8 Inch Mown Cable
120 do 6 1/2 do Hansen

The Surveyor to state the present Condition of

Upper Deck Fastenings _____

Spirketting _____

Plank Shears _____

Topsides _____

Upper Deck with its Appendages _____

Lower Deck Fastenings _____

Wales _____

Counter _____

Plank and Treennails
 (Outside to the Water's Edge.) _____

Rudder _____

Windlass Patent

Capstan _____

General Observations and Opinion,
 as required by the Instructions,

This ship is now complete in her
equipment and may in the opinion
be deemed fit

The Amount of Fee..... £ : : is received by me.

Committee Minute _____ 183

Character assigned _____

Lloyd's Register
 Foundation