

REPORT of SURVEY for REPAIRS.

No. 3338 Survey held at London Date May 1st 1837
 on the Brig Britannia Master Tratton
 Tonnage 190 Built at Bideford When built 1810
 By whom built _____ Owners Lezlie
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock Lincoln Dock

Original Survey, No. 594, 14/15/232 Dated 1834 Clap'd A

Port London

Repairs.

At the present time in consequence of damage
 shipped, caused from keel to waterway beam
 wood shunters & Coppered -
 New upper piece of Stem & Upper - New rigging -
 2 Stakes doubling wrought under the deck & the
 keel generally overhauled

The Surveyor to state the present Condition of

Upper Deck Fastenings _____
 Spirketting _____
 Plank Shears _____
 Topsides _____
 Upper Deck with its Appendages _____
 Lower Deck Fastenings _____

Wales _____
 Counter _____
 Plank and Treennails
 (Outside to the Water's Edge) _____
 Rudder _____
 Windlass _____
 Capstan _____

General Observations and Opinion,
 as required by the Instructions,

Most Shipping Steels in good order
 This keel has scuttled firmly in her bottom
 & is now in any opinion eligible to remain
 in her present Clap A

George Bayley

The Amount of Fee £ 1 : 1 : - is received by me. Tratton

Committee Minute 12 May 1837

Character assigned Not under repair